

1/43

Fig. 1






Fig. 2




Fig. 2A




Fig. 2C






Fig. 2B















Fig. 6



exploded view

Fig. 6A



perspective view



9/43

Fig. 7




Fig. 8

10/43




Fig. 8A




Fig. 8B




Fig. 9




Fig. 9B




Fig. 9A




Fig. 10




Fig. 10A

13/43




Fig. 11




Fig. 11A




Fig. 12




Fig. 12A

16/43







Fig. 13






Fig. 14





Fig. 14A



down into bore hole

Fig. 14B





Fig. 14C



22/43






Fig. 15B

Fig. 16

23/43

Fig. 16A




Fig. 17




Fig. 18







Fig. 19






Fig. 20B





Fig. 20C








Fig. 22





**Fig. 23**

31/43




Fig. 24

32/43






Fig. 25

33/43




Fig. 26




Fig. 27




Fig. 28




Fig. 29




Fig. 30




Fig. 31A




Fig. 32





Fig. 32A





**Fig. 33**

41/43




Fig. 34




Fig. 35

43/43

